

### 3 MEASURE FOR JOBST MEDICAL LEGWEAR

#### Measuring positions

##### **cH – Hip**

Circumference at largest dimension around buttocks.

##### **cG – Thigh**


Circumference at largest dimension.

##### **cC – Calf**

Circumference at largest dimension.

##### **cB – Ankle**

Circumference at smallest dimension.



#### Provide the following measurements for:

Knee High – cB & cC

Thigh High – cB, cC & cG

Waist high – cB, cG & cH

- Each leg is measured independently
- Measure in the early morning when possible as swelling occurs later in the day